



## State of Utah

### Department of Natural Resources

MICHAEL R. STYLER  
*Executive Director*

### Division of Oil, Gas & Mining

JOHN R. BAZA  
*Division Director*

JON M. HUNTSMAN, JR.  
*Governor*

GARY R. HERBERT  
*Lieutenant Governor*

#### Representatives Present During the Inspection:

Company Scott Dimick Superintendent

OGM Pete Hess Environmental Scientist III

## Inspection Report

Permit Number:	<b>C0070033</b>
Inspection Type:	PARTIAL
Inspection Date:	Thursday, May 19, 2005
Start Date/Time:	5/19/2005 8:15:00 AM
End Date/Time:	5/19/2005 9:00:00 AM
Last Inspection:	Wednesday, April 20, 2005

Inspector: Pete Hess, Environmental Scientist III

Weather: Sunny, clear, warm, 50's F.

InspectionID Report Number: 610

Accepted by: whedberg  
6/8/2005

Permittee: **ANDALEX RESOURCES INC TOWER DIVISION**

Operator: **ANDALEX RESOURCES INC TOWER DIVISION**

Site: **WILDCAT LOADOUT**

Address: **PO BOX 902, PRICE UT 84501**

County: **CARBON**

Permit Type: **PERMANENT COAL PROGRAM**

Permit Status: **ACTIVE**

#### Current Acreages

100.00	<b>Total Permitted</b>
63.70	<b>Total Disturbed</b>
	<b>Phase I</b>
	<b>Phase II</b>
	<b>Phase III</b>

#### Mineral Ownership

- ☒ Federal  
☐ State  
☐ County  
☐ Fee  
☐ Other

#### Types of Operations

- ☐ Underground  
☐ Surface  
☒ Loadout  
☒ Processing  
☐ Reprocessing

#### Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

With the exception of the pending Division Order for the Wildcat permit area, there are no other compliance actions. The Permittee has responded to the Division's initial comments; the review of that response is underway/pending.

Inspector's Signature

Date

Thursday, May 19, 2005

Pete Hess, Environmental Scientist III

Inspector ID Number: 46

**Note:** This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801  
telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • [www.ogm.utah.gov](http://www.ogm.utah.gov)

Permit Number: C0070033  
 Inspection Type: PARTIAL  
 Inspection Date: Thursday, May 19, 2005

## Inspection Continuation Sheet

Page 2 of 3

### **REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS**

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

### **3. Topsoil**

The protective vegetative cover on the soil storage piles adjacent to pond "E" and "F" appears to be flourishing, more than likely due to the wet spring which the area has had up to this point.

### **4.b Hydrologic Balance: Sediment Ponds and Impoundments**

Ponds "C" and "F" contained some water. There were no compliance issues noted for any of the ponds.

### **4.d Hydrologic Balance: Water Monitoring**

There was no flow observed in Wildcat Wash this day.

### **9. Protection of Fish, Wildlife and Related Environmental Issues**

The undisturbed vegetation in the disturbed area east of the main stockpile area and NW of topsoil stockpile "A" was observed and photographed. All species appear to be flourishing as of today's inspection.

### **16.a Roads: Construction, Maintenance, Surfacing**

All of the site's frequently traveled roads were in a graded, well-compacted condition. Mr. Dimick indicated that he has obtained purchase costs for road gravel and magnesium chloride for the site. The application of same appears to be scheduled for the near future.

### **20. Air Quality Permit**

Opacity levels of fugitive road dust were observed behind several of the dual trailer coal trucks accessing the area. The levels appear to be below the 20% level required by the Permittee's air quality approval order. A water truck operated by D&D Equipment and Supply (under contract by the Permittee) was observed to be accessing the disturbed area near the end of the inspection. Road watering was discussed with Mr. Dimick. The Division representative indicated that as ambient air temperatures increase and relative humidity levels decrease, an increase in watering frequency will be necessary to keep the site in compliance.